

Test Report

Number : TWNC00552406

Applicant: Tian Hong Fiber Co., Ltd.
No.121, Sec. 1, Xizun St.,
Shulin Dist., New Taipei City 238,
Taiwan, R.O.C.

Date : Oct 07, 2016

Sample Description:


One (1) groups of submitted samples said to be :

Item Name	: Grey Blanket
Item No.	: BS620MATTBE
Manufacturer	: Tian Hong Fiber Co., Ltd.
Buyer	: Cal-Comp Big Data, Inc.
Country of Origin	: Taiwan
Goods Exported to	: All Around the World
Date Sample Received	: Sep 30, 2016
Date Test Started	: Oct 04, 2016

Test Conducted:

As requested by the applicant, for details please refer to attached pages.

Authorized by:
On Behalf of Intertek Testing Services
Taiwan Limited



K. Y. Liang
Director





Number : TWNC00552406

Test Conducted :

1. Total Lead (Pb) Content

With reference to USEPA 3050B/3051, acid digestion method was used and by Atomic Absorption Spectrophotometer (AAS) Analysis.

<u>Tested Sample</u>	<u>Result (ppm)</u>
Metal Yarn	ND
Elastic Band	ND

Remarks : ppm = Parts per million = mg/kg
ND = Not detected
Detection Limit = 10 ppm
The elastic band tested sample was not totally digested


2. Phthalates Content

According to CPSIA Test Method: CPSC-CH-C1001-09.3, by solvent extraction and Gas Chromatography-Mass Spectrometer (GC-MS) analysis.

<u>Compound</u>	<u>Result (%)</u>
	<u>Elastic Band</u>
Diethyl hexyl phthalate (DEHP)	ND
Dibutyl phthalate (DBP)	ND
Benzyl butyl phthalate (BBP)	ND
Di-(iso-nonyl) phthalate (DINP)	ND
Di-(iso-decyl) phthalate (DIDP)	ND
Di-(n-octyl) phthalate (DNOP)	ND

Remarks: % = Percentage based on weight of tested sample
ND = Not detected
Detection limit = 0.005% (for each compound)





End of Report

Except where explicitly agreed in writing, all work and services performed by Intertek is subject to our standard Terms and Conditions which can be obtained at our website: <http://www.intertek-twn.com/terms/> . Intertek's responsibility and liability are limited to the terms and conditions of the agreement.

This report is made solely on the basis of your instructions and / or information and materials supplied by you and provide no warranty on the tested sample(s) be truly representative of the sample source. The report is not intended to be a recommendation for any particular course of action, you are responsible for acting as you see fit on the basis of the report results. Intertek is under no obligation to refer to or report upon any facts or circumstances which are outside the specific instructions received and accepts no responsibility to any parties whatsoever, following the issue of the report, for any matters arising outside the agreed scope of the works. This report does not discharge or release you from your legal obligations and duties to any other person. You are the only one authorized to permit copying or distribution of this report (and then only in its entirety). Any such third parties to whom this report may be circulated rely on the content of the report solely at their own risk.

